

www.plutusonline.com

XTREME
PARTS WASH®

XTREME® Parts Wash

- ◆ **remove heavy grease and oil, industrial coatings, Cosmoline, fabrication process and paint line residues, and light rust**
- ◆ **XTREME® is the excellent choice for use in industrial hot wash and vapor blast systems**
- ◆ **XTREME® radically reduces part reject rates and weld failures**
- ◆ **XTREME® is the excellent choice for use in industrial hot wash and vapor blast systems. XTREME® radically reduces part reject rates and weld failures**
- ◆ **XTREME® is the best stainless cleaner available, and does not contain abrasives, hydrocarbons, butyl, and has no flashpoint**

XTREME Parts Wash® is a 0-0-0 Hazmat Rated parts cleaning solution that is designed to remove heavy grease and oil, industrial coatings, Cosmoline, fabrication process and paint line residues, and light rust.

XTREME® is formulated to EPA LD50 Guidelines and to be California Code 65 safe. XTREME® will actually increase biological activity in industrial

waste streams, but will kill bacteria, fungus and microbes on treated parts and in equipment systems.

XTREME® is the excellent choice for use in industrial hot wash and vapor blast systems. XTREME® radically reduces part reject rates and weld failures.

XTREME® is a concentrated formulation that can be mixed onsite to provide the correct strength or dilution for your particular situation.

One gallon of XTREME® added to the normal water volume in hot cleaning systems would out perform dry additives at a 5-10 cost saving ratio. The hard, baked on buildup will begin to emulsify immediately on contact with the XTREME®. The parts will be cleaner. The system operating temperature may be significantly lowered.

Nozzles, spray arms and supply lines stay clean and open. Oils and greases are broken down so there are less associated disposal costs and maintenance downtime problems.

Skin rash and irritation in most skin types is eliminated. Breathing concerns and clothing damage are eliminated. No more chemical burns and health hazards.

XTREME® may be used full strength or diluted depending upon the residue or contamination being removed. Applied via a spray bottle, XTREME® is the ideal bench top cleaner for hand cleaning parts, tools and workspaces. XTREME® is the best

stainless cleaner available, and does not contain abrasives, butyl, hydrocarbons, and has no flashpoint.

XTREME® is used in all size and type parts washers, hot or cold. Dilution is discretionary depending on the nature of the surface being cleaned and the contamination that is being removed.

XTREME® is safe for all industrial materials that are normally used in fabrication operations. XTREME® does not damage decals, hoses, and finishes, gaskets, lenses, seals or equipment.

DO NOT USE XTREME® Parts Wash on Silicone or Aluminum Parts or Equipment.

XTREME® should be used in vapor blast systems in accordance with system manufacturer's instructions. To maintain the effectiveness of XTREME®, oil accumulations on the surface of the washer reservoir should be periodically removed. This will extend the effective life of the product.

